






FIG. 3

















FIG. 6







10/29

FIG. 9






FIG. 10








FIG. 13


FIG. 13

SIDE VIEW OF UPPER MOUNT

FIG. 13

TOP VIEW OF COLUMN (HANDLE INSERT ABSENT)

FIG. 14



CUTAWAY SIDE VIEW OF LOWER MOUNT







FIG. 16



15/29 FIG. 17













FIG. 19A





19/29 FIG. 19B




20/29










23/29











FIG. 23B





27/29



2516 2506b 2506a 2550 2502 2518 2521 2521 2520 2508 2508 2508

28/29

FIG. 25B




FIG. 25C




FIG. 26A




FIG. 26B

2604 2610 2610

FIG. 26C

